

FIG. 1




FIG. 1A




FIG. 1B




FIG. 1C




FIG. 1D



FIG. 2




FIG. 4




FIG. 3




FIG. 5




FIG. 6




FIG. 7




FIG. 8

2040ED 46T600T





FIG. 9



(SOFT START)
FIG. 10





FIG. 11



SHUT DOWN CIRCUITS

FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18